



Borescope Inspection Result Form

ENGINE TYPE	A/C	Eng. SN	POS	TSN	CSN	PLACE
CF6-80C2A2	YA-CAV	695404	# 1	58188:56	25031	KBL
Reason BSI	Log book item					

LPC (booster)	Sub_Ref	AMM 72-31-00		
	Rev_No	68	Rev. Date	JUNE 01 2021
Remarks:				
No SIGNIFICANT DEFECTS NOTED				

HPC	Sub_Ref	AMM 72-31-00		
	Rev_No	68	Rev. Date	JUNE 01 2021
Remarks:				
No SIGNIFICANT DEFECTS NOTED				

CC & NGVs	Sub_Ref	AMM 72-41-00, AMM 72-51-00		
	Rev_No	68	Rev. Date	JUNE 01 2015/2017
Remarks:				
No SIGNIFICANT DEFECTS NOTED				

HPT turbine and blades	Sub_Ref	AMM 72-53-00		
	Rev_No	68	Rev. Date	JUNE 01 2021
Remarks:				
One blade with missing material on area B beyond AMM limit, missing material and radial cracks on several blades, coating has gone on most of the blades. HPT STG2: Nicks on several blades L/E has been observed.				

LPT blades	Sub_Ref	AMM 72-57-00		
	Rev_No	68	Rev. Date	JUNE 01 2015
Remarks:				
No SIGNIFICANT DEFECTS NOTED				

If hand cranking cover is removed, hand cranking must be installed	Performed by	Inspected by
	Fraidoon Azimi	Ah. Siar Rahat
Inspected Date:	30/Nov/2025	Signature
Engine Condition	Unserviceable	Stamp